

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

Marquette COUNTY


T 43 N R 25-24W

DESCRIPTION OF CORNER Section corners T43N 1/6 T43N
R25W 12/7 R24W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 12-1-72 F. J. Bray

WITNESSES TO CORNER..... 12" W. Pine (S6) (NBT) N43°E 28.7'



4" B. Spruce (S12) (NBT) S84°W 15.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set from one original witness in poor condition (Tam 12 S59°W 14')

Five witness were originally marked for this corner only three stump bottoms
remaining beside witness found.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

12-20-72