

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY  
T 43 N R 24W

DESCRIPTION OF CORNER South 1/16 corner for sections 7/8

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-11-72 F. J. Bray

WITNESSES TO CORNER..... 9" Cedar ( S 1/16 ) (BT) S 60° W, 15.6'



12" Cedar ( S 1/16 ) (B2) S 08° E, 17.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between the section corners  
to the south and  $\frac{1}{4}$  corner to the north.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE 11-17-72