MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43 NR_24_W_-T 43 NR 25 W

			Marquette COUNTY
DESCRIPTION	OF	CORNER	Rection Corner common to Sections 30,31,25,26
DESCRIPTION	OF	CORNER	MONUMENT_1 Pipe with 4 Brass cap
WIT TNESSES	то	CORNER	_12" Ceder - 8 40 E - 17 Links
			10" Ceder - N 88 W - 10 Links
			_6% Goder - N_47 E = 12_Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Two original B.T.'s in place, one down, in fair condition.

Corner was placed and witnessed June 21, 1951.

SURVEYORS SEAL

SIGNED SURVEYOR DATE _7/25/51