

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. $\frac{42}{43}$ N.R. 24 W


Marquette COUNTY

DESCRIPTION OF CORNER W 1/16 corner for sections $\frac{32}{5}$

CORNER MONUMENT 1" iron pipe 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/24/69, F. J. Bray

WITNESSES TO CORNER..... 9" W. Spruce (W 1/16) (BT) S 50° W, 43 links



4" W. Spruce (W 1/16) (BT) N 37° W, 43½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed at 1" iron pipe as set by Marquette County Road Commission crew.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/6/69
REGISTERED LAND SURVEYOR

Frank J. Bray