MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_43 NR_25 N

llarquetteC	OUNTY
DESCRIPTION OF CORNER Section corner common to Sections 14, 15, 22 a	nd.23.
DESCRIPTION OF CORNER MONUMENT_l"_Pipe_with_4" Brass_Cap	
WITNESSES TO CORNER _ 8" Cedar _ N 61 V _ 30 Links _ (S 15 MPT)	
6" Cedar N 44 E 27 Links (S 14 MBT)	
ll"_CedarS_19 E 19 Links (S_23 NET)_	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Cedar bearing S 70 W, 19 Links. Tree down and in poor condition. Several scribe marks plain.

Corner lies in swamp.

Corner found by Art Enger, Assistant District Forester.

Corner placed and witnessed on 11 August 1958 with Enger.

SURVEYORS SEAL

IGNED____Billy

Billy D. Buckler

DATE 5-13-59

REGISTERED LAND SURVEYOR