CONS. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 43 NR 25 - 26 W

				Marq	uette .		<u>986.                                     </u>	COUN	1T.
DESCRIPTION	OF	CORNER	Section co	mer com	on to Sec	etions 19,	_30, 2/	4_and 2	5.
DESCRIPTION	OF	CORNER	MONUMENT	l" Pipe	with 4"	Brass Cap	' <b>-</b>		
WITNESSES '	ТО	CORNER _	_&"_Aspen_	_ N_29 W	7_L;	ink <b>s (</b>	\$ _24 M	PT)	
			9" Hemlock	s 61 E	64 L	inks (	S_3 <u>0</u> 1 <u>0</u>	. <b>_ (T</b> S	-
						·		<b>-</b>	-
							. <b></b> -		_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Cedar B.T.'s bearing N 52 E, 13 Links and N 77 W, 42 Links. Both B.T.'s in poor condition.

Corner was found by Art Enger, Assistant District Forester.

Corner was placed and witnessed on 11 August 1958 with Enger.

SURVEYORS SEAL

SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 5-13-59\_