

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 25 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 27-34

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10-23-63

WITNESSES TO CORNER..... 8" Cedar (1/4S NBT) N 85° W 09 links



CIRCLE CORNER REGISTERED

8" Cedar (1/4S NBT) N 34° E 22 links

Trees marked by County Road Commission

9" Cedar (1/4S) N 39° E 12½ links

AND  
12" W. Birch (1/4 S 27, T43NR26W) N 46° W 27½ links

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was replaced as set by Marquette County Road Commission. Found 3/4" Iron Pipe and Wood Post at Corner with new witnesses.

Found remains of Tamarack bearing trees at S 60° W 10 links and N 22° E 39 links. Both in fair condition.

Corner lies 1/2 chain west of old logging road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 24, 1964  
REGISTERED LAND SURVEYOR  
Billy D. Buckler