

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R s 25 & 26 W

DESCRIPTION OF CORNER Section corner for sections T43N R26W <sup>25/30</sup>/<sub>36/31</sub> T43N R25W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/11/69, F. J. Bray

WITNESSES TO CORNER..... 8" Elm (S. 25) (NBT) N 43° W, 233½ links



11" Elm (S. 36) (NBT) S 77° W, 166½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2" iron shaft set by Marquette County Road Commission from one original B.T. found in 1928.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

9/25/69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68