

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 25 W

DESCRIPTION OF CORNER Section corner for sections $\frac{20}{21}$ $\frac{29}{28}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/5/69

WITNESSES TO CORNER..... 20" W. Pine (S.28) (NBT) S 34° E, 80 links



8" Cedar (S.29) (NBT) S 60° W, 71½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from B.T. to SW a rotted stump with overgrowth of notch and face. Rotted wood for B.T. to NE found by survey crew.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 9/25/69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68