

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43N R 25W

DESCRIPTION OF CORNER 1/4 corner for sections $\frac{29}{32}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/27/69, F. J. Bray with B. McDonald

WITNESSES TO CORNER..... 7" H. Maple (1/4 S) (NBT) N 31° E, 10½ links



12" H. Maple (1/4 S) (NBT) N 62° W, 53 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 1½" iron shaft set by Marquette County Road Comm. who at that time noted an original B.T. stump. No original evidence found at the present time.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 9/25/69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68