MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND . CORNER RECORD

T 43 NR 25 M T 43 NR 26 W

| | | | - | | _Marquette | C | YTAUC |
|-------------|----|--------|----------------|------------|----------------|--------------|-------|
| DESCRIPTION | OF | CORNER | Section Corner | common | to Sections | 6,7,1,12 | |
| DESCRIPTION | OF | CORNER | MONUMENT_1 | Pipe w | ith &™ Brass (| gap | |
| WIT TNESSES | то | CORNER | 6* Cedar - 1 | N 88 E - | 6_Links | | |
| | | | 10" Cedar1 | N_ 25 JV . | - 22 Links _ | | |
| | | | 10" Cedar - | ē 80 M | 46 Links _ | - | |
| | | | | | | | |
| | | | | | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. One original B.T. in place, in good condition.

Corner was placed and witnessed December 12, 1951.

SURVEYORS SEAL

SIGNED SEM C. SEEM NOTE 1/14/52 REGISTERED LAND SURVEYOR