## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T.43. NR.25.W.

			Marquette COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner- between Sections-7-& 8
DESCRIPTION	OF	CORNER	MONUMENT_1/2" Iron_Bar
WIT TNESSES	то	CORNER	6* Spruce - 8 14 E - 37 Links
			6" Cedar Stub - 8 85 W - 12 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Corner had been previously located and perpetuated by unknown Surveyor. Two original B.T.'s in place, in good condition.

Corner was rewitnessed October 24, 1951.

SURVEYORS SEAL

SIGNED SIENE L. Safa Malu DATE 11/1/51
REGISTERED LAND SURVEYOR