MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43 NR_25 W_ T_44 NR_25 W

	i'arquetteCOUNT'
DESCRIPTION OF CORN	ER 1/4 Corner between Sections 5 & 32
DESCRIPTION OF CORN	ER MONUMENT 1" Pipe with 4" Brass cop
WITTNESSES TO CORN	ER 20" Dry Cedar - N 30 N - 73 Links
	24" Spruce - S 63 E - 142 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Survey Crew, while working in this Township. Corner had been previously located by County Survey crew. One original B.T. still in place, but in poor condition.

Corner was placed and witnessed March 7, 1951.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 3/8/51