

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR. 25 W.
T. 44 N.R. 25 W.

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3, 4, 33, 34.

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap.

WITNESSES TO CORNER 10" Cedar - S 13 W - 35 Links

5" Cedar - N 41 W - 36 Links


10" Cedar - N 17 E - 68 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Survey crew while working on the subdivision of section 4, T 43 N R 25 W. One original B.T. still in place, but in poor condition.

Corner was placed and witnessed October 10, 1950.

SURVEYORS SEAL



SIGNED John C. Seale DATE 11/1/50
REGISTERED LAND SURVEYOR