MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43 NR_25_W₁_ T 44 NR 25 W

			Marquette COUNTY
DESCRIPTION	OF	CORNER	Section corner common to sections 4,5,32,33.
DESCRIPTION	OF	CORNER	MONUMENT_1"_pipe_with_4" Brass_cap.
WIT TNESSES	то	CORNER	10" Spruce - N 40 E - 29 Links
			8* Spruce - S 88 E - 35 Links
			6# Spruce - S 43 W - 27 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was established by proportionate measurement, by Forestry Division Survey crew, while subdividing section 4, T 43 N R 25 W.

Two probable original B.T.'s, in place, one rotted, one badly burned.

Corner placed and witnessed October 10, 1950.

NOV 9 1950
FORESTRY DIV.
CONSERVATION DEPT.

SURVEYORS SEAL

SIGNED SLAW C Sen Mater DATE 11/7/50 REGISTERED LAND SURVEYOR