

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 25. W. 1.
T. 44. NR. 25. W.

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 4 and 33. -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" Brass cap. -----

WITNESSES TO CORNER 6" Spruce - S 5 W - 25 Links -----


5" Spruce - S 48 W - 26 Links -----

5" Spruce - N 51 W - 16 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Area badly burned. Established by proportionate measurement. Line tree identification made east of this corner.
Corner placed and witnessed October 11, 1950.

SURVEYORS SEAL



SIGNED Jean C. DeLuca DATE 11/7/50
REGISTERED LAND SURVEYOR