MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43. NR__ %_ T

			Marquette COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 4 & 5
DESCRIPTION	OF	CORNER	MONUMENT_1. Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	_ 8" Cadar - N 70 W - 28 Links
		,	8#_Cedar 8 10 F - 31 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cermer was established, by proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this area. In the absence of any definite original evidence, corner was placed in line, at proportional distance between the two Section Corners.

Corner was placed and witnessed April 20, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 12/2/