

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26W

DESCRIPTION OF CORNER Section corner for Sections  $\frac{27/26}{34/35}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-19-72 F. J. Bray

WITNESSES TO CORNER..... 12" Cedar (S35) (NBT) S 85° E, 51.2'



4" Dead Cedar (NBT) S 66° W, 29.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 3/4" iron pipe as set by Marquette County Road Commission. Pine B.T. to NE is down with faint scribe marks visible on faces.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J Bray

DATE

11-16-72