

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26

DESCRIPTION OF CORNER Section Corner for Sections $\frac{21}{22}$
 $\frac{28}{27}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-12-72 F. J. Bray

WITNESSES TO CORNER..... 7" Cedar (S22) (NBT) N48°E, 19.7'



12" Cedar stump (NBT) S15°W, 29.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from ~~an~~ old scribed post. Rotted tamarack stump to the SW checks well for bearing and distance. Marquette County Road Commission has notes of this corner in their files dated in the early 1920's.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-15-72