

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26W

DESCRIPTION OF CORNER North 1/16 corner for sections 30/29

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-27-72 F. J. Bray

WITNESSES TO CORNER..... 5" B. Spruce (N 1/16) (BT) N 02° E, 11.4'



8" Cedar (N 1/16) (BT) S 47° E, 16.3'

3/4" Iron pipe N57° E, 24.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between the section corner to the north and 1/4 corner to the south. 3/4" iron pipe set in single strand wire fence by unknown party.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J Bray

DATE

11-16-72