

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY
T 43 N R 26W

DESCRIPTION OF CORNER North 1/16 corner for sections 29/28

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-15-72 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (N 1/16) (BT) N43°W, 14.9'



6" Cedar (N 1/16) (BT) S 25°W, 14.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between the section corner
to the north and $\frac{1}{4}$ corner to the south.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J Bray

DATE

11-16-72