

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26 W

DESCRIPTION OF CORNER East 1/16 Corner for sections $\frac{27}{34}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-19-72 F. J. Bray

WITNESSES TO CORNER..... 14" Cedar (E 1/16) (BT) N 51 W, 28.9'



14" Cedar (E 1/16) (BT) S 45 W, 20.2''

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between the section corner to the east and $\frac{1}{4}$ corner to the west. Down scribe wood post found where corner was placed.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-24-72