

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY  
T 43 N R 26W

DESCRIPTION OF CORNER ¼ Corner for Sections 30/29

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-29-72 F. J. Bray

WITNESSES TO CORNER..... 9" leaning cedar (¼S) (NBT) N63°E, 8.8'



10" Cedar (¼S) (NBT) S35°W, 3.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at steel fence post which was recorded by Marquette County Road Commission. Sawyer Stoll Forester remembers a B.T. present in the 1930's. Old blaze on cedar faces corner.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

11-16-72