STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

					Marquet	te col	INTY
				τ _	43 √	R _261	1
DESCRIPTION OF CORNER	<u> </u>	orner fo	r Sections	29/28			
CORNER MONUMENT	iron pipe	with 4"	aluminum	сар		· · · · · · · · · · · · · · · · · · ·	
DATE MONUMENT PLACED AND W	ITNESSED		9-15-7	2 F.	J. Bray	,	
WITNESSES TO CORNER	8"	spruce,	876° E, 14	.6'			
N 2 8			N35 ⁰ W, 12.				
	AND						
CIRCLE CORNER REGISTERED)						
DESCRIPTION IN DETAIL AS TO	U HOW COR	NER WAS L	OCATED AND	IDENI	IFIED O	R RESTORED	٠.
en 1			hataaan a			. +a +ba	
This corner was placed mid	way and c	n a line	between s	ection	corners	, to the	
north and to the south.	orner lie	s in the	east marg	in of a	small	opening.	
SURVEYOR'S SEAL							
SIO	GNED Z	EGISTERED		EYOR	DATE	11-16-	72
Forestry Division, Lansin	a	Frank	J. Bray				
- oresert protection, paneru	4						
	_					τ	404
	_					_	ev.