

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26W

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for Sections $\frac{21}{28}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-12-72 F. J. Bray

WITNESSES TO CORNER..... 14" Cedar ($\frac{1}{4}$ S) (NBT) N33^o W, 25.3'



10" Cedar ($\frac{1}{4}$ S) (NBT) N 61^o E, 35.7'

6" Balsam, squared, with tag, N 82^o W, 1.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from notes obtained from the Marquette County Road Commission. Notes stated, wood post found NW, 3.0' of 40" pine stub in the early 1920's. Stub now a rotted stump bottom. Blazes face corner.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J Bray

DATE

11-17-72