

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26W

DESCRIPTION OF CORNER $\frac{1}{4}$ corner for sections ²⁸ 33

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-22-72 F. J. Bray

WITNESSES TO CORNER..... 6" B. Spruce ($\frac{1}{2}$ S) (NBT) N50° W, 10.2'



6" Cedar ($\frac{1}{2}$ S) (NBT) S 19° W, 19.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on a line between section corners to the east and to the west. No original evidence found. Blazed dead tamarack stub is near.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-16-72