

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26W

DESCRIPTION OF CORNER 1/4 Corner for Sections 20
29

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-29-72 F. J. Bray

WITNESSES TO CORNER..... B.T.s by Marquette County Road Commission.



12" Cedar (S29 T43 NR 26W) S62° W, 21.8'

10" Cedar (1/4 S) (S20) N 01° W, 3.7'

AND

12" Cedar (signature tree) N23° E, 4.4'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed at 3/4" iron pipe as set by the Marquette County Road Commission in the 1920's. They found wood post and signature tree at this location. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11-17-72