

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY  
T 43 N R 26 W

DESCRIPTION OF CORNER 1/4 corner for Sections 33/34

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED June 15, 1972

WITNESSES TO CORNER..... 4" Cedar (1/4S) (NEE) S74°W, 21.2'



4" B. Spruce (1/4S) (NEE) N48°W, 12.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set from the notes of Marcus McNabb, Surveyor. Tamarack 3"  
N40°W, 28.7'; Tamarack 3" S50°W, 15.0' - both these witnesses green and standing.  
Corner lies 16.5' west of  $\emptyset$  of present road. Squared post found.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE 8-11-72