

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 N R 26 W

DESCRIPTION OF CORNER Section corner for Sections <sup>20/21</sup>~~29/28~~

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED July 12, 1972 F. J. Bray

WITNESSES TO CORNER..... Marquette County Road Commission Witnesses:



11" Spruce (S.20,T43N-R26W) N27°W, 20.8'

10" Cedar (S.28,T43N-R26W) S76°E, 5.7'

New Witness:

7" Cedar (S.21) (NET) N23°E, 12.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from a 3/4" iron pipe set by the Marquette County Road Commission. They stated original evidence was found in the 1920's.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

8-11-72