

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44 N.R. 23-24 W

Marquette COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18, 19, 13, 24

CORNER MONUMENT 1" Pipe with 4" Brass Cap


DATE MONUMENT PLACED AND WITNESSED 6/5/61

WITNESSES TO CORNER....8" Balsam (S 19 NBT) S 20° E 55 Links

9" Cedar (S 13 NBT) N 52° W 89 1/2 Links

BT marked by Marquette County Road Commission.

AND  
14" Soft Maple (S 18, T44N, R23W) N 40° E 82 Links



DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marquette County Road Commission. Found 3/4" Iron Pipe and Wood Post in place. No positive evidence of original B.T.'s. Corner lies in North edge of swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 21, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler