

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 23 W.

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 13, 14, 23, 24

DESCRIPTION OF CORNER MONUMENT Pipe not set

WITNESSES TO CORNER 10" White Pine N 72° E 124 links

9" Cedar S 36° E 108 links

Cedar post set 10 feet South of true location of

corner.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Corner from one White Pine B.T. in good condition.

Corner lies in E. and W. road.

Corner shown to us by Arne Metsa, District Forester.

Corner re-witnessed April 17, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 4/19/56  
REGISTERED LAND SURVEYOR