

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 . NR 23 W. .

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section corner common to sections 29, 30, 31, 32 . . .

DESCRIPTION OF CORNER MONUMENT 1" Iron pipe with 4" Brass cap. . . .

WITNESSES TO CORNER 10" Tamarack - N 38 E - 95 Links . . .

10" Cedar - S 16 W - 77 Links . . .

-----

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Corner was found by District Forester Metsa, of Gwinn. One B.T., in good condition, still plainly seen; but because of erosion by Spring floods, is probably unstable.

Corner placed and witnessed September 13, 1950.

SURVEYORS SEAL

SIGNED James C. Seale Water DATE 9/20/50 . . .  
REGISTERED LAND SURVEYOR