

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~44-45~~NR. 23 W. . .

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 4-5-32-33 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER	11" W. Pine	N 54° W	54 links
		"S32 NBT"	
	7" B. Spruce	S 37° E	16½ links
		"S4 NBT"	
	6" B. Spruce	S 40° W	16 links
		"S5 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one hemlock B.T. bearing N 45° W 12 links in excellent condition. Stump broken off 5' high.

Placed location poster on old R.R. Grade 1½ chs east of corner.

Corner shown to us by Art Enger, Ass't Forester.

SURVEYORS SEAL

SIGNED Billy D. Ruckles DATE 3/6/57
REGISTERED LAND SURVEYOR