LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:			CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	_ T. <u>44</u>	N. S., R. 24	■. W. –	H-2
2. PROPERTY CONTROLL- 3 ING IN SECTION	,T44	N. S., R. <u>24</u>	E. W	3
3, MISCELLANEOUS PROPERTY IN SECTION	,T	N. S., R.	E.	
4. LOT NO, RECO	RDED PLAT	·	···	

MARQUETTE

5. PRIVATE CLAIMS ______ REGISTER OF DEEDS STAMP AND FILING NUMBER

A. Description of original monument and accessories and/or subsequent restoration:

- H-2 C. 1/4 Cor. of Sec. 3; Marquette Co. Road Comm. center Cor. Circ. iron rod Dry Cedar 7" N31°E 15.7'; Cedar 8" N12°W 31.8'.
 - 3 N 1/16 Cor. on the West Sec. line of Sec. 3; not previously established.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- H-2 Set at the intersection of the N-S and E-W 1/4 lines of Sec. 3. Found iron rod set by Marquette Co. Rd. Comm. 18.3' N39°E of this Mon. Found error in Road Comm. computations plus incorrect method used.
 - 3 Set on line and proportionate distance between the West 1/4 Cor. and the N.W. Sec. Cor. of Sec. 3.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-2 D.N.R. Mon.; 6" Cedar S56 $^{\circ}$ W 22.3'; 4" Cedar N74 $^{\circ}$ W 5.4'; 3" Cedar N25 $^{\circ}$ E 2.0'; 3" Cedar S82 $^{\circ}$ E 21.5'.
 - 3 D.N.R. Mon.; 6" Cedar N22°W 27.7'; 6" Cedar S66°W 5.95'; 9" Cedar N72°E 4.8'; 7" Cedar S13°E 14.55'.

SIGNED BY Lavil B. Walkit DATE 9-15-83

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558