

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 . NR . 25 . W.

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Meander corner on West side of Escanaba River on
North side of Section 5, T.44 N.R.25 W.

DESCRIPTION OF CORNER MONUMENT 1" Iron pipe with 4" Brass cap

WITNESSES TO CORNER 20" Cedar - S 4 E - 37 Links

16" Balsam - S 21 W - 4 Links

4" S. Maple - N 27 W - 15 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Corner was located by District Forester Metsa, of Gwinn. When I
saw the corner, one of the original B.T.'s, a cedar, was still plainly visible
and in good condition. Definitely an original corner.

This corner was set on July 18, 1950.

SURVEYORS SEAL

SIGNED

Jean C. Lepa Metsa
REGISTERED LAND SURVEYOR

DATE 9/20/50