

MAR 1 9 1999

MARQUETTE COUNTY RECEIVED FOR RECORD

1998 DEC 16 PM 3: 21

100	اعرص الماتي	1	3.5
SE	الا		IV

For corners in

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Policies	a. Monley	
REGISTER	OF DEEDS	•

MARQUETTE (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>45N</u> R <u>25W</u> T <u>44N</u> R <u>25W</u> TR TR	-13 -1
 Property Controlling in Section Miscellaneous 	S T R S T R S T R	
Property in Sec. 4. Lot No , Re	S T R	

LIBER R 2 PAGE 80

Register of Deeds Stamp & File Number

, in a field survey on GERALD W. CARLSON **APRIL** <u>30TH</u>, 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: I-13: Corner common to Sections 34 and 35, T45N-R25W; and Sections 2 and 3, T44N-R25W.

1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:

6" Spruce

N27E,

25 L

7" Spruce

N36W,

10 L

1852:Martin M. Hall's original subdivision survey notes for T44N-R25W describe the corner monument as a wood post referenced by: S57W, 10" Spruce S17E. 10 L 10" Spruce 12 L

1910: Charles Cummings, in Record of Surveys pp. 118-119, indicates the corner as being on-line between the South 1/4 Corner of Section 35 and the corner of Sections 34 and 35 (he probably meant the corner of Sections 33 and 34). Distance East to South 1/4 Corner of Section 35 is 2640', and Distance North to West 1/4 Corner of Section 35 is 2624.25'. No accessories given.

No Date: A survey sketch from the personal notes of R.A. Brotherton, copied by R.J. Brotherton in 1968, indicates the corner. Distance East of 2640' to the South 1/4 Corner of Section 35. Distance North of 2624.5' to the West 1/4 Corner of Section 35. An interior angle of 89-45' is shown between the South Section Line and the West Section Line of section 35. No accessories given.

1941: Survey field notes from M.C.R.C. F.B. #703 (no pg. shown) indicate the corner as an "Iron Pipe in swamp". No accessories given. (SEE REVERSE SIDE)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-13: 1998: No original corner evidence found, Found and accepted a 2" O.D. Iron Pipe, 0.80' above ground, and +/- 75' East of a clearing. Bearings and distances to remaining 3 found references check very well with those recorded in L. 5, RC Pg. 39. Checked Line Call:(Leave Swamp Course N.E. & N.W. 4.50 chains [297'] South of Corner). Measured Call: South, 280', Leave Swamp Course N.E. & N.W. Distance East is 2639.26'. Distance West is 2638.30'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-13: 1998: Bolted a 3 1/4" diameter aluminum tablet Marquette County Survey Monument, stamped to identify the corner, on top of found 2" O.D. Iron Pipe. Monument is 0.80' above ground. Measured to existing d.h. nails and washers in found references:

S50E,

5.57' (Carlson NBT)

Spruce

S19W,

2

3

4

13.35' (Carlson NBT)

14" J. Pine 7" Spruce

Established new references:

N50W.

16.94' (Carlson NBT)

37.91

9" Spruce

N25E.

Surveyor's Michigan License No.

Green Steel Sign Post w/ Yellow Survey Marker Sign

N40F.

2.01

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, GROUP and stamped B.T. Tags affixed.

E 13 N 2, 1998

GERALD W CARLSON SURVEYOR No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

SURVEY & REMONUMENTATION

WAR 1 9 1999

<u>l-13:</u>

PART A CONTINUED: SECTION

No Date: M.C.R.C. Government Index Books #641 and #643 indicate the corner as an Iron Pipe in Swamp. No accessories given.

1982: A Certificate of Survey by Gerald W. Carlson P.S. #24589 for the Minatome Corporation (No Liber or page given), indicates the corner as a monumented corner. Distance N89-22'-44"E, 2639.29' to the South 1/4 Corner of Section 35. Distance S89-22'-30"W, 2638.28' to the South 1/4 Corner of Section 34. No accessories given.

1982: An LCRC recorded by Gerald W. Carlson P.S. #24589 in L. 5, RC Pg. 39, indicates the corner as a found Iron Pipe, 8" high. He set a 2" X 2" X 4 stake alongside pipe. Referenced by:

11" J. Pine

S46E,

5.58'

6"

S23W,

13.391

6" Spruce

N51W,

16.91'

Spruce J. Pine

N43E.

27.80