Cons. 4047 4/55

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

7.44 NR 26 W.

			Marquette COUNIN
DESCRIPTION	OF	CORNER	1/4 cor. between secs: 9-16
DESCRIPTION	OF	CORNER	MONUMENT1" Pipe with 4" Brass Cap
WITNESSES	то	CORNER .	9" B. Spruce (1/45 NBT) S25 E 14 Lks.
			9"_Balsam_(1/4s_NBT)_N75_W28_Lks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cor. from one W. Pine B.T. bearing N56°E 04½ Lks. bottom of B.T. remains on stp. Poor Condition. Cor. lies 1 ch. north of swamp edge. Cor. placed and wit. 1/30/59 with Art Enger, Ass't D.F.

SURVEYORS SEAL

Billy D. Buckles

SIGNED Billy D. Buckler DATE 8/6/59