MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T44 NR 26 W

		Marquette	COUNTY
DESCRIPTION OF CORN	ER 1/4 Corner b	etween_Sections 25,	26
DESCRIPTION OF CORNE	R MONUMENT_1	" iron pipe with 4"	brass cap
WITNESSES TO CORNER	Su Cedar	N_62 ⁰ B	14_links
	6π Cedar	N 26° W	22½ links
	ָריי יֹן	/4 s nbt"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from two tamarack B.T.s; one poor condition, one good condition, down.

1/4 Corner lies in Swamp.

Squared and scribed 5" Cedar, 4 links East of 1/4 Corner.

1/4 Corner found by Arne Metsa, District Forester, while cruising timber.

No evidence of use apparent.

Corner placed and witnessed 1/18/57.

SURVEYORS SEAL

SIGNED Billy & Buckles DATE 2-7-57