

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 30W


Dickinson COUNTY

DESCRIPTION OF CORNER ¼ corner for Secs. 23 and 26.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5-20-63

WITNESSES TO CORNER..... 8" Cedar (¼ S.) (N.B.T.) N. 28° E., 17 Lks.



10" Cedar (N.B.T.) S. 88° W., 06 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from wood post and tamarack. Rotted stump with notch visible (Tam. 18" S. 46° E., 40 Lks.). Signature tree with dates back to 1900.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/2/63
REGISTERED LAND SURVEYOR