

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 30 W.


Dickinson COUNTY

DESCRIPTION OF CORNER E. 1/16 corner for Sections 23 and 26.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5/24/63.

WITNESSES TO CORNER..... 6" Spruce (B.T.) N. 47° E., 37 Lks.



5" (Twin) S. Maple (B.T.) S. 49° W., 56 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed Midway and on Line between section corner to East and 1/4 corner to West.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-5-63
REGISTERED LAND SURVEYOR