CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 44N N.R. 30W

		Dickinson	COUNTY
DESCRIPTION OF CORNER	West 1/8 corner for section	ns <u>25</u>	
	l" iron pipe with 4" brass	36	
DATE MONUMENT PLACED AND	WITNESSED 9/21/62		<u>.</u>
WITHESSES TO CORNER	5" Y. Pine (BT) S87°W,	16 links	
N	22" W. Pine stump (BT)		
3 6	6" W. Spruce (BT) N66°	E, 42½ links	
	AND		
CIRCLE CORNER REGISTERED	<del></del>		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner to west and 1/4 corner to east.

SURVEYOR'S SEAL

SIGNED Silly & Suchler DATE January 17, 1963
REGUSTERED LAND BURVEYOR

Billy D. Buckler