

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 44 N.R. 29 & 30 W

Dickinson COUNTY


T 44 N T 44 N

DESCRIPTION OF CORNER N 1/16 Corner for R 30 W 25/30 R 29 W

CORNER MONUMENT 1" Iron Pipe with 1/2" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/25/63

WITNESSES TO CORNER..... North Edge of Boulder S 30° W 10 1/2 links



6" H. Maple (N 1/16) (BT) S 80° W 26 "

5" H. Maple (In Clump)(N 1/16)(BT) S 73° E 06 1/2 "

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on Line between Section Corner to North and 1/4 Corner to South.

SURVEYOR'S SEAL

SIGNED Billy D. Bucklar DATE 3/5/65  
REGISTERED LAND SURVEYOR  
Billy D. Bucklar