

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N. R. 22-23W


Alger-Marquette COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 19-30-24-25

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/26/64 with Arthur Klawiter

WITNESSES TO CORNER..... 9" Hard Maple (S19 NBT) N71°E 14.1 Feet



8" Hard Maple (S24 NBT) N40°W 16.6 Feet

10" Soft Maple (S25 NBT) S45°W 10.5 Feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at Wood Post. Found two Y. Birch Stump bottoms in proper position for Original Bearing Trees. Distance South and West to Stream checks.

SURVEYOR'S SEAL

SIGNED Billy E. Buckler DATE 8/4/1964
REGISTERED LAND SURVEYOR