CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 45 H.R. 23 W

	<u>Marquette</u>	COUNTY
DESCRIPTION OF CORNER	Section Corner for Sections 16-17-20-21	
CORNER MONUMENT	1" Pipe with 4" Aluminum Cap	<del></del>
DATE MONUMENT PLACED AT	ID WITHESSED 3-13-62 with A. Metsa, District Forester	
WITHESSES TO CORNER	9# Soft Maple (S 21 NBT) S 80° E 39 links	
N21	8# Soft Maple Twin (S 16 NBT) N 27°E 60 links	<del> </del>
CIRCLE CORNER REGISTERS	AND	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Commer was replaced from two original B.T.'s. A Y. Birch (green) bearing S  $42^{10}$  W 15 links and a Hemlock stub bearing N  $45^{0}$  E 08 links. Hemlock tree lying on ground with upper face and scribe marks in good condition.

SURVEYOR'S SEAL

SIGNED Silly Suckles, DATE 10-28-63

REGISTERED LAND SURVEYOR

Billy D. Buckler