LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Land Marie Control of the Control of

=0	R CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	MARQUETTE
•	PUBLIC LAND SURVEY		E-3	Co.
1,	•			. •
2.	PROPERTY CONTROLL-),T. 45 S., R. 24 E.	1.3	
3.	MISCELLANEOUS PROPERTY IN SECTION			·
4.	4. LOT NO, RECORDED PLAT			
	PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, David B. Babbitt do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on September 23, 19 76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19—, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:				
A. Description of original monument and accessories and/or subsequent restoration: E-3 N.W. Section corner; Wood post - Maple 10 - S65°E - 32 lks.; birch 14 - S31°W - 31 lks.				
1 W. 1/16 corner on the north section; not previously established.				
3 N. 1/16 corner on West section line; not previously established.				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
E-3 Set by double proportion to G.L.O. record using & cors.; % mile east and 1% miles south and section corners 1 mile west and 1 mile north.				
1	. Set M.P.O.L. between the N.W. section corner and Nt corner.			
3	and the west & corner.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: All - 1" pipe, 4" aluminum cap, cedar post.				
E-3	7" J. pine - N56°E - 19.65'; 8" J. pine - S76°W - 14.6'; 3" spruce - N39°W - 49.5'			
1	12% cedar - S25°W - 37.4'; 8" spruce-N70°W - 24.9'; 7" cedar - N9°E - 45.15'.			
	13" j. pine - 548°E - 66.4'; 8" j. pine - S67°E - 88.1'			
		·	•	
	SIGNED BY DATE			
	SIGNED BY	<u> </u>	DATE	
	SURVEYOR'S MICHIGAN	REGISTRATION NO.		(SEAL)
	FOR STATE AND UNITED STATES AGENCIES:			
	SIGNED BY DATE DATE			
	APPROVED AND SIGNED	ВҮ	n I AND SHRVEYOR	*
	-			