

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 45 .. NR. 24 .. W

.. Marquette .. COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 21, 22, 27, 28

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 15" Y. Birch (S 22 NBT) N 65° E 42 1/2 Links

13" Y. Birch (S 27 NBT) S 51° E 54 1/2 Links

B.T.'s marked by County Road Commission

8" B. Spruce N 17° W 22 Links

8" B. Ash N 46° E 25 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced as set by Marquette County Road Commission.

Found 3/4" Iron Pipe in place with Cedar B.T. (down) bearing S 52° E 25 Links.

Corner was placed and witnessed November 13, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/28/60
REGISTERED LAND SURVEYOR
Billy D. Buckler