

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 45. NR. 24. W.

Marquette COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 20, 21, 28, 29

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" W. Pine (NBT) S 58° W 04 Links

14" W. Pine (NBT) S 13° E 33 Links

13" W. Pine (NBT) N 78° E 24 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced as set by unknown surveyor. Found 2" Iron Pipe with place with rotted W. Pine stump bearing N 58° E 17 Links. Found old chopping but no identifying marks. Distance is longer than record to North and West.

Corner was placed and witnessed November 13, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/27/60
REGISTERED LAND SURVEYOR
Billy D. Buckler