

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 45 N R 24 W

DESCRIPTION OF CORNER North 1/16 corner for Section 20

CORNER MONUMENT 1 1/2"x30" iron pipe

DATE MONUMENT PLACED AND WITNESSED June 27, 1972

WITNESSES TO CORNER..... 8" Tamarack (BT) N58°E, 52.7'



13" W. Pine (BT) S01°W, 83.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from witnesses furnished by Northern Michigan Engineers Inc. who set this corner in 1959. Iron they set missing, possibly due to road construction.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

8-11-72