LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
I. PUBLIC LAND SURVEY	T N. R E. W.		6
2. PROPERTY CONTROLL- ING IN SECTION—	2 ,T. 45N N. 24W E. W.	2, 3, 6	
3. MISCELLANEOUS PROPERTY IN SECTION —	,T		
4. LOT NO , R	ECORDED PLAT		
5. PRIVATE CLAIMS			
			REGISTER OF DEEDS STAMP AND FILING NUMBER

- David P. Babbitt ____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 26, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on______, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:
- A. Description of original monument and accessories and/or subsequent restoration:
- 2 East 1/16 Cor. on the Morth Sec. line of Sec. 28; not previously established.
- 3 N. 1/16 Cor. on the West Sec. line of Sec. 28; not previously established.
- 6 NE 1/16 on Sec. 28; not previously established.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner;
- 2 Set M.P.O.L. between the North 1/4 Cor. and the M.E. Sec. Cor. of Sec. 28. A 3/4" iron rod (not of record) bears N39°W 49.55' from Cor. Mon.
- 3 Set M.P.O.L. between the W. 1/4 Cor. and the N.W. Sec. Cor. of Sec. 28. A 3/4" iron rod, not of record, bears S51 W 12.5' from Cor. Mon.
- 6 Set at the computed Ctr. of the N.E. 4 of Sec. 28 by closed traverse.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 2 1" pipe, 4" aluminum cap; 7" Spruce N85 0 W 13.0'; 7" B1. Cherry N8 0 W 27.7'; 6" B1. Cherry N71 0 E 38.3'; 5" Spruce S11 0 E 17.75'; 3/4" iron rod N39 0 W -
- 3 19 pipe, 4" aluminum cap; 4" Bl. Spruce S71°E 19.7'; 6" Bl. Spruce M22°E 21.2'; 5" Bl. Spruce S4°W 10.7'; 5" Tam. M81°W 13.8'; 3/4" iron rod-S51°W 12.5'. 6 1" pipe, 4" aluminum cap; 20" W. Pine M87°W 18.5'; 6" B. Spruce S42°W 22.2'; 12" B. Spruce S16°E 50.0'; 7" R. Maple S76°E 11.8'.

SURVEYOR'S MICHIGAN REGISTRATION NO.