

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45 N.R. 25 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 22-23

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/28/64

WITNESSES TO CORNER..... 8" Jackpine (1/4 S NBT), S88°E, 9.0'



8" Jackpine (1/4 S NBT), N02°W, 15.5'

6" Jackpine (1/4 S NBT), S51°W, 14.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at a 3/4" Iron Pipe placed by unknown person. Found lines run South, East and West from this Corners

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 9/29/1964